OFE

02922.000071 <u>PATENT</u>

PE VO IN TO

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

TOHRU OHSAKA

TOHRU OHSAKA

Appln. No.: 10/046,163

Filed: January 16, 2002

For: MULTI-LAYERED PRINTED WIRING BOARD

Examiner: Jeremy C. Norris

Group Art Unit: 2827

Certificate

JAN 0 5 2005

U.S. Patent No.: 6,800,814 B2

Issued: October 5, 2004 : December 29, 2004

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

12/30/2004 CNGUYEN 00000040 6800814

01 FC:1811

of Correction

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentee Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

467121v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,800,814 B2

DATED

October 5, 2004

INVENTOR(S) :

TOHRU OHSAKA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3

Line 14, "annulus" should read --an annulus--;

Line 17, "power supply" should read --signal--; and

Line 52, "annulus." should read --an annulus.--.

COLUMN 4

Line 17, "annulus." should read -- an annulus.--.

COLUMN 5

Line 22, "plane. This" should read --plane, this--.

COLUMN 7

Line 42, "gournd" should read --ground--.

COLUMN 9

Line 1, "Further," should read --Further, when--; and Line 63, "layer 4" should read --layer 14--.

COLUMN 10

Line 9, "illustrated" should read --illustrated,--;

Line 17, "layer 3," should read --layer 13,--;

Line 37, "FIG. 15D," should read --FIG. 5D,--;

Line 50, "part 7c" should read --part 17c--; and

Line 59, "layer 4," should read --layer 14,--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,800,814 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

467121v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,800,814 B2

DATED

October 5, 2004

INVENTOR(S) :

TOHRU OHSAKA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 11, "26a to 26h" should read --16a to 16h--; and Line 55, "second" should read --third--.

COLUMN 12

Line 22, "part 2c" should read --part 27c--; and Line 38, "layer 11" should read --layer 21--.

COLUMN 15

Line 53, "layers each at least having at least three wiring" should be deleted.

COLUMN 16

Line 11, "around" should read --ground--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,800,814 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

467121v1

□⇒ ____

Stable Here Outly TER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,800,814 B2

DATED

October 5, 2004

INVENTOR(S) :

TOHRU OHSAKA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 3

Line 14, "annulus" should read -- an annulus--;

Line 17, "power supply" should read --signal--; and

Line 52, "annulus." should read -- an annulus.--

COLUMN 4

Line 17, "annulus." should read -- an annulus.--.

COLUMN 5

Line 22, "plane. This" should read --plane, this--.

COLUMN 7

Line 42, "gournd" should read --ground--.

COLUMN 9

Line 1, "Further," should read --Further, when--; and Line 63, "layer 4" should read --layer 14--.

COLUMN 10

Line 9, "illustrated" should read --illustrated,--;

Line 17, "layer 3," should read --layer 13,--;

Line 37, "FIG. 15D," should read --FIG. 5D,--;

Line 50, "part 7c" should read --part 17c--; and

Line 59, "layer 4," should read --layer 14,--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,800,814 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

467121v1

No. of add'l. copies @ 30¢ per page

ightharpoons -

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,800,814 B2

DATED

October 5, 2004

INVENTOR(S) :

TOHRU OHSAKA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 11, "26a to 26h" should read --16a to 16h--; and Line 55, "second" should read --third--.

COLUMN 12

Line 22, "part 2c" should read --part 27c--; and Line 38, "layer 11" should read --layer 21--.

COLUMN 15

Line 53, "layers each at least having at least three wiring" should be deleted.

COLUMN 16

Line 11, "around" should read --ground--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,800,814 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

467121v1

